



Photo 1 – Gravel Driveway – Courtesy of FAA



Photo 2 – Close Up of Gravel Driveway – Courtesy of FAA



Photo 3 – Lawn – Courtesy of FAA



Photo 4 – Opening in Woods – Courtesy of FAA



Photo 5 – Left Wing – Courtesy of FAA



Photo 6 – Right Side View of Main Wreckage – Courtesy of FAA



Photo 7 – Left Side View of Main Wreckage – Courtesy of FAA



Photo 8 – Aft Fuselage – Courtesy of FAA



Photo 9 – Right Wing Courtesy of FAA



Photo 10 – Front View of Main Wreckage



Photo 11 – Rear View of Main Wreckage



Photo 12 – Flap Handle (0-Degree Position)



Photo 13 – Pitch Trim Indicator (Takeoff Position)



Photo 14 – Carburetor Heat Control Knob (As Found Position)



Photo 15 – Close Up of Carburetor Heat Control Knob



Photo 16 – Carburetor Heat Door (As Found Position)



Photo 17 – Carburetor Heat Door (Closed Position)



Photo 18 – Fuel Strainer




Photo 19 – Interior View of Carburetor Throat and Float Bowl



Photo 20 – Carburetor Floats