



Investigative Photographs

ERA21LA314

Peter Wentz

Air Safety Investigator

Eastern Region Aviation

Photographs provided by the Federal Aviation Administration.



Photograph 1 – Accident airplane – Front view.



Photograph 2 – Accident airplane – Right side view.



Photograph 3 – Accident airplane – Left side view.



Photograph 4 – Accident airplane – Right wing damage.



Photograph 5 – Accident airplane – Left wing damage.



Photograph 6 – Accident airplane – Broken motor mount.