



Photo 1 – Right side view of airplane after it was recovered and placed on jacks (courtesy of insurance company).



Photo 2 – Damage to lower fuselage (courtesy FAA)



Photo 3 - Damage to lower fuselage (courtesy FAA)