



Photo 1 – View of left side of airplane showing collapsed gear and wing damage. (Courtesy of FAA)



Photo 2 – Closeup view of collapsed gear. (Courtesy of FAA)



Photo 3 – View of wing damage. (Courtesy of FAA)



Photo 4 – Right side of airplane profile showing overall damage. (Courtesy of FAA)