

NTSB ERA21LA322

N906ER | Diamond DA42

Photo Array



Photo 1 – View of the accident airplane at the accident site (Photo Courtesy of FAA)



Photo 2 – View of the accident airplane and overview of the landing area (Photo Courtesy of FAA)



Photo 3 – View of the accident airplane’s left wing, flaps, and landing gear (Photo Courtesy of FAA)



Photo 4 – View of the accident airplane's right wing (Photo Courtesy of FAA)



Photo 5 – View of the accident airplane's left propeller and wing (Photo Courtesy of FAA)



Photo 6 – View of the accident airplane's right propeller and wing (Photo Courtesy of FAA)



Photo 7 – View of the accident airplane's flight controls and overview of the cockpit (Photo Courtesy of FAA)




Photo 8 – View of the accident airplane’s circuit breaker panel with the autopilot pulled and collared (Photo Courtesy of FAA)



Photo 9 – View of the accident airplane's manual elevator trim and checklist located on floor (Photo Courtesy of FAA)