



Investigative Photographs

ERA21LA330

Peter Wentz

Air Safety Investigator

Eastern Region Aviation

Photographs provide by the Civil Air Patrol



Photograph 1 – Accident glider – Left wing leading edge damage.



Photograph 2 – Accident Glider – Left wing total damage.



Photograph 3 – Accident glider – (Close-up) Left wing leading edge rib damage.