



**Photo 1 – Main Wreckage (FAA Photo)**



**Photo 2 – Runway Scrape Marks (FAA Photo)**



**Photo 3 – Upper Fuselage and Empennage (FAA Photo)**



**Photo 4 – Empennage Damage (FAA Photo)**