



Investigative Photographs

ERA21LA366

Peter Wentz
Air Safety Investigator
Eastern Region Aviation

Photographs Provided by the Federal Aviation Administration



Photograph 1 – Accident balloon – envelope.



Photograph 2 – Accident balloon – envelope.



Photograph 3 – Accident balloon – Basket frame and fuel tanks.



Photograph 4 – Accident balloon – Basket frame and fuel tanks.