



Photo 1 – View of Wreckage as Found Facing Direction of Travel (FAA)



09/20/2021 11:03

Photo 2 – View of Wreckage as Found Facing Opposite Direction of Travel (FAA)



Photo 3 – View of Damaged Wing Strut (FAA)