



Photo 1 – Right Wing Root (FAA Photo)



Photo 2 – Right Wing Damage (FAA Photo)



Photo 3 – Right Wing Damage (FAA Photo)