



Photo 1 – View of damaged vertical stabilizer and rudder. (Courtesy of FAA)



Photo 2 – Closeup view of damaged vertical stabilizer. (Courtesy of FAA)



Photo 3 – Right side view of damaged vertical stabilizer and rudder. (Courtesy of FAA)