



Photo 1 – View of right wing damage. (Courtesy of Pilot/Owner)



Photo 2 – View of collapsed nose landing gear folded up under fuselage. (Courtesy of Pilot/Owner)



Photo 3 –View of damage to engine cowl and propeller. (Courtesy of Pilot/Owner)