

[ERA22FA010]

INVESTIGATION PHOTOGRAPHS



Photograph 1 – View of Helicopter from Right Side



Photograph 2 –View of Helicopter from Rear



Photograph 3 – View of Helicopter from Left Side



Photograph 4 – View of Helicopter from Front



Photograph 5 – Main Rotor Fragments – Tip A



Photograph 6 – Main Rotor Fragments – Tip B



Photograph 7 – Tail Rotor Gearbox and Blades