



Photo 1 – Main Wreckage (NTSB Photo)



Photo 2 - Main Wreckage (NTSB Photo)



Photo 3 - Main Wreckage (NTSB Photo)



Photo 4 - Main Wreckage (NTSB Photo)



Photo 5 – Engine and Propeller (NTSB Photo)



Photo 6 – Propeller Blade (NTSB Photo)



Photo 7 – Vacuum Pump Drive (NTSB Photo)



Photo 8 – Vacuum Pump Body (NTSB Photo)