



Photo 1 – Main Wreckage (NTSB Photo)



Photo 2 – Tree Strike (NTSB Photo)



Photo 3 – Aft Fuselage and Tail Boom (NTSB Photo)



Photo 4 – Cockpit (NTSB Photo)



Photo 5 – Main Rotor Hub (NTSB Photo)



Photo 6 – Main Rotor Blade and Hub (NTSB Photo)



Photo 7 – Tail Rotor (NTSB Photo)



Photo 8 – Tail Rotor Hub (NTSB Photo)



Photo 9 – Landing Gear Parts (NTSB Photo)



Photo 10 – Instrument Panel (NTSB Photo)



Photo 11 – Engine (NTSB Photo)



Photo 12 – V-Belts on Upper Sheave (NTSB Photo)



Photo 13 – Spark Plugs (Lycoming Photo)