

ERA22FA141

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Overhead view of airplane where it came to rest. (Courtesy of St. Augustine Fire Rescue)



Photograph 2 - View of the airplane inverted in the marsh.



Photograph 3 - Side view of the airplane after recovery. (Courtesy of Lycoming)



Photograph 4 - Top view of engine after recovery.



Photograph 6 - View of right side of engine. (Courtesy of Lycoming)



Photograph 7 - View of left side of engine. (Courtesy of Lycoming)



Photograph 8 - View of the spark plugs. (Courtesy of Lycoming)



Photograph 9 - View of the remaining propeller blade and two partial blades. (Courtesy of Lycoming)