



Photo 1 – Skid Marks – Courtesy of BMFD



Photo 2 – Continuation of Skid Marks



Photo 3 – Witness Mark on Base of Taxiway Light



Photo 4 – Witness Mark on Nose Wheel Landing Gear Assembly



Photo 5 – Main Wreckage



Photo 6 – Close Up of Main Wreckage



Photo 7 – Right Wing



Photo 8 – Pitot Tube with Cover Installed (As Found)



Photo 9 – Pitot Tube with Cover Removed



Photo 10 – Engine After Removal from Firewall



Photo 11 – Left Wheel and Brake Assembly



Photo 12 – Right Wheel and Brake Assembly



Photo 13 - Cockpit



Photo 14 – Left (Pilot's) Seat Belt



Photo 15 -Right Seat Belt



Photo 16 – ELT with Switch in “OFF” Position (As Found)