



**Photo 1 – cut powerlines with main wreckage in background**



**Photo 2 – cut powerlines**



**Photo 3 – main wreckage with cut powerline in background**



**Photo 4 – Main wreckage, engine**



**Photo 5 – Powerline impression mark on landing light housing**



**Photo 6 – Powerline impression mark on bottom of helicopter**



**Photo 7 – powerline impression mark on bottom of helicopter**



**Photo 8 – High voltage power line cut, laying on ground**



**Photo 9 – high voltage power lines cut and broken**