



Photo 1 – Main Wreckage (NTSB Photo)



Photo 2 – Point of Initial Ground Impact (NTSB Photo)



Photo 3 - Main Wreckage (NTSB Photo)



Photo 4 - Main Wreckage (NTSB Photo)



Photo 5 - Cockpit and Cabin (NTSB Photo)



Photo 6 – Right Wing (NTSB Photo)



Photo 7 – Left Wing (NTSB Photo)



Photo 8 – Engine and Propeller (NTSB Photo)



Photo 9 – Left Magneto (NTSB Photo)




Photo 10 – Spark Plugs (NTSB Photo)