


[ERA22FA226]


INVESTIGATION PHOTOGRAPHS



Photograph 1 - Rear View of North Bound Vehicle



Photograph 2 - Front View of Southbound Vehicle



Photograph 3 - Left Side View of Southbound Vehicle



Photograph 4 - Debris from Airplane and Southbound Vehicle



Photograph 5 - Witness Marks on Median



Photograph 6 - Tire Mark on Median



Photograph 7 - Main Wreckage



Photograph 8 - Right Side View of Main Wreckage



Photograph 9 - Rear View of Main Wreckage



Photograph 10 - Left Side View of Main Wreckage



Photograph 11 - Propeller Blade No. 1



Photograph 12 - Propeller Blade No. 2




Photograph 13 - Main Cabin Area




Photograph 14 - Nose Section




Photograph 15 - Instrument Panel



Photograph 16 - Engine



Photograph 17 - Carburetor



Photograph 18 - Carburetor Float Bowl



Photograph 19 - Carburetor Floats and Accelerator Pump



Photograph 20 - Carburetor Floats and Float Valve




Photograph 21 - Bottom Spark Plugs



Photograph 22 - Top Spark Plugs (First Photo)



Photograph 23 - Top Spark Plugs (Second Photo)




Photograph 24 - Fuel Strainer Bowl



Photograph 25 - Fuel Strainer Screen




Photograph 26 - Right Cylinder Bank



Photograph 27 - Left Cylinder Bank



Photograph 28 - Fuel System Finger Screens



Photograph 29 - Air Filter



Photograph 30 - Carburetor Heat Air Valve (Open)



Photograph 31 - Carburetor Heat Air Valve (Closed)