

ERA22FA227

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of Glider from Right Side



Photograph 2 - View of Glider from Left Side



Photograph 3 - View of Glider from Rear



Photograph 4 - View of Glider from Front



Photograph 5 - View of Struck Tree



Photograph 6 - View of Debris Path