



Photo 1 – View of Helicopter as Found (FAA)



Photo 2 – View of Emergency Pedal Stop Release in Deployed Position (Bell)



Photo 3 – View of Emergency Pedal Release Proximity to Pilot’s Collective Control (Bell)



Photo 4 – View of Exemplar Tailrotor Crosshead Fully Assembled and Safety-Wired (Bell)



Photo 5 – View of Tailrotor Crosshead/Driveplate Assembly as Found (Bell)