

ENSTROM HELICOPTER LOG			
Owner		Agri Air	
Registration		N600TA	
Model Number		F-28F	
Serial Number		704	
Date	Meter	TTAF	Description of work performed
04/24/22		2656.3	1) Replaced air filter p/n BA-15
			2) Serviced tailrotor and main rotor gear boxes w/ Mobil 1 75W90 gear oil
			3) Lubricated all other points w/ Aeroshell 22 or 14 grease as applicable
			4) Installed overhauled lower swash plate assembly p/n 28-16101-101 s/n 19283-005
			5) Installed serviceable idler support yoke p/n 28-13292-1
			6) Installed new bushing for belt tension strap
			7) Installed new pinion nut p/n 28-13184-11
			8) Installed new Upper Jackstrut Bearing Assy. p/n 28-13170-903
			9) Installed new Rod end Belt tension pulley p/n ECD091-1
			10) Installed new Taper pin tail rotor drive shaft 28-13623-17
			11) Installed serviceable Main rotor gear box p/n 28-13170-3-R s/n 88-308-81C
			12) Installed new idler bearings p/n ECD018-11 s/n 20223-03 & 20223-04
			13) Installed new Tail rotor pitch link rod ends p/n 11-691-04 & 11-691-05
			14) Installed rivnuts for tail boom strobe light, and replaced ground wire
			15) Remove Dynon artificial horizon
			16) Relocated mount for spray system screens
			17) Wired copilot push to talk switch
			18) C/W SB 0124 Landing gear clamp inspection, No defects noted
			19) C/W AD 90-17-02 Tailrotor drive shaft coupling inspection, No defects noted
			20) C/W AD 82-24-01 Clutch mechanism, No defects noted
			21) C/W AD 88-11-06 Horizontal stab inspection, No defects noted
			22) Con't....

ENGINE LOG

Photo 1 – Last Airframe Annual, Page 1

