

ERA22FA344

Satellite Image of Accident Site

Legend

 Items of Interest

Secondary Flight Instrument Panel
Flotation Cushion

Stick Grip

Seat back Cushion
Main Wreckage

Right Main Landing Gear Wheel Pant

Separated Main Rotor Blade

Meirose Rd

Meirose Rd

Meirose Rd

Meirose Rd

6828

Google Earth

Image © 2024 Airbus



100 ft