

ERA22FA386

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Front View of Wreckage (NTSB)




Photograph 2 - Rear View of Wreckage (NTSB)




Photograph 3 - Angular Cut Wood at Accident Site (NTSB)



Photograph 4 - Engine (NTSB)



Photograph 5 - Tire Marks of Runway (NTSB)



Photograph 6 - Measurements of Tire Marks on runway (NTSB)