



Photo 1 – Main wreckage, tail view



Photo 2 – Main wreckage side view



Photo 3 – Engine and gearbox



Photo 4 – cockpit and instrument panel



Photo 5 – engine with rotation buckling