

ERA22FA422

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Main Wreckage



Photograph 2 - Canopy Latch Outer Handle (Courtesy of MCSO)



Photograph 3 - Canopy Latch Inner Handle



Photograph 4 - Attached Propeller Blade



Photograph 5 - Separated Propeller Blade



Photograph 6 - Fuel Filter



Photograph 7 - Throttle and Choke Levers