



Photo 1 – Main Wreckage



Photo 2 – Close Up of Main Wreckage



Photo 3 – First Tree Strike



Photo 4 – Right Wingtip Cap



Photo 5 – Front View of Wreckage



Photo 6 – Top View of Wreckage



Photo 7 – Left Wing



Photo 8 – Propeller and Spinner



Photo 9 – Right Side View of Wreckage



Photo 10 - Empennage



Photo 11 – Bottom of Horizontal Stabilizers and Elevators



Photo 12 – Bottom of Left Wing



Photo 13 – Bottom of Right Wing