



Photo 1 – Taxi Lane – Courtesy of FAA



Photo 2 – Right Rear Corner of Fuel Truck – Courtesy of FAA



Photo 3 – Scratches and Rub Marks on Fuel Truck – Courtesy of FAA



Photo 4 – Ladder Grab on Fuel Truck – Courtesy of FAA



Photo 5 – Side View of Ladder Grab – Courtesy



Photo 6 – Fuel Truck Location – Courtesy of FAA



Photo 7 – Damage to King Air – Courtesy of FAA



Photo 8 – Right Wing – Courtesy of FAA



Photo 9 – Close Up of Right Wing – Courtesy of FAA