



Photo 1 – Insurance Adjuster Digital Photograph. View in Front of the Airplane Looking Aft.



Photo 2 - Insurance Adjuster Digital Photograph. View of The Left Side of the Fuselage Between the Firewall and Front Portion of the Door. White Arrows denote Locations of Compression Wrinkles.



Photo 3 - Insurance Adjuster Digital Photograph. View of The Right Side of the Fuselage Between the Firewall and Front Portion of the Door. White Arrows denote Locations of Compression Wrinkles.



Photo 4 - Insurance Adjuster Digital Photograph. View of The Right Side of the Fuselage At the Main Landing Gear Attach. Note the Slight Deformation.



Photo 5 – Digital Photograph From Flight Instructor. View From Aft Looking Forward Showing Damage to Lower portion of Bulkhead Assembly Part Number 1712105-1 at Fuselage Station 281.48