



Photo 1 – View of Ground Track Facing Opposite Direction of Travel (FAA)



Photo 2 – View of Ground Track Facing Direction of Travel (FAA)



Photo 3 – View of Ground Scars and Wreckage as Found Facing Direction of Travel (FAA)



Photo 4 – View of Damage to Right Wing (FAA)