



Photo 1 – View of front of airplane showing left wing damage.



Photo 2 – View of right side of airplane showing horizontal stabilizer damage.