

NTSB ERA22LA030

N6888A, C172

Photo Array



Photo 1 – View of the accident airplane at the accident site (Photo Courtesy of FAA)



Photo 2 – View of the fuselage substantial damage (Photo Courtesy of FAA)



Photos 3, 4 – View of damaged elevator and right aileron surfaces (Photo Courtesy of FAA)