



Photo 1 – FAA Digital Photograph. View Taken Forward of the Airplane at the Accident Site Looking Aft. Note the left wing leading edge Rotated down About 90 Degrees.