



Investigative Photographs

ERA22LA038

Peter Wentz
Air Safety Investigator
Eastern Region Aviation



Photograph 1¹ – Accident airplane – left side view.

¹ Photograph provided by Federal Aviation Administration.



Photograph 2² – Accident airplane – right wing and strut damage.

² Photograph provided by Federal Aviation Administration.



Photograph 3³ – Accident airplane – Rudder damage.

³ Photograph provided by Federal Aviation Administration.