



Photo 1 – View of Main Wreckage facing Opposite Direction of Travel (Pilot)



Photo 2 - View of Helicopter Right Side facing Downhill (Pilot)




Photo 3 - Comparative View of Damaged Timing Case and Accessory Drive Gears (FAA)