



Photo 1 – View of underbelly of airplane damaged by gear up landing.




Photo 2 – View of pilots pre-landing checklist showing “gear down” as step three.