

NTSB ERA22LA072

N47523, Aeronca, O-58B

Photo Array



Photo 1 – View of the accident airplane and the fuselage damage (Photo Courtesy of FAA)



Photo 2 – Additional view of the fuselage damage (Photo Courtesy of FAA)



Photo 3 – View of the runway and ground scar marks (Photo Courtesy of FAA)



Photos 4, 5, 6— View of the metal pole, destroyed bird house, and runway environment (Photo Courtesy of FAA)