



Photo 1 – Main Wreckage (Photo Courtesy of FAA)



Photo 2 – Separated Left Wing (Photo Courtesy of FAA)



Photo 3 – View Back Toward Runway (Photo Courtesy of FAA)



Photo 4 – Skid Marks Near Touchdown (Photo Courtesy of FAA)



Photo 5 – Skid Mark Travelling Off Runway (Photo Courtesy of FAA)



Photo 6 – Tire Tracks in Grass (Photo Courtesy of FAA)