



Photo 1 – Accident Site – Courtesy of FAA



Photo 2 – Main Wreckage – Courtesy of FAA



Photo 3 – Close Up of Main Wreckage – Courtesy of FAA



12/01/2021 11:28

Photo 4 – Rear View of Main Wreckage – Courtesy of FAA



Photo 5 – Right Side of Main Wreckage – Courtesy of FAA



Photo 6 – Engine and Propeller – Courtesy of FAA



Photo 7 – Internal Fuselage Damage – Courtesy of FAA




Photo 8 – Fuel Selector Panel – Courtesy of FAA



Photo 9 – Right Fuel Quantity Indicator – Courtesy of FAA



Photo 10 – Left Fuel Quantity Indicator – Courtesy of FAA



Photo 11 – Top of Left Fuel Tank



Photo 12 – Bottom of Left Fuel Tank




Photo 13 – Fuel System Schematic – Courtesy of FAA



Photo 14 – Accident Airplane’s Modified Fuel System



Photo 15 – Close Up of Modifications to Header Tank



Photo 16 -Bottom of Header Tank



Photo 17 – Gascolator Bowl



Photo 18 – Carburetor Float Bowl