

ERA22LA104

INVESTIGATION PHOTOGRAPHS




Photograph 1 - View of left rear quarter of airplane at accident site. (Courtesy of FAA)



Photograph 2 - Forward front view of airplane looking aft showing damage. (Courtesy of FAA)



Photograph 3 - View of left front side of airplane showing damage. (Courtesy of FAA)



Photograph 4 -Top of engine case showing hole and damaged parts. (Courtesy of FAA)