

NTSB ERA22LA183

N9440D, Cessna 172RG

Photo Array



Photo 1: Overview of the airplane at the accident site (Photo Courtesy of FAA)



Photo 2: Overview of the airplane at the accident site (Photo Courtesy of FAA)



Photo 3: View of the fuselage damage near the rudder pedals (Photo Courtesy of FAA)



Photo 4: View of the rudder control surface damage (Photo Courtesy of FAA)



Photo 5: View of the fuselage damage near the nose landing gear (Photo Courtesy of FAA)