



MEMORANDUM FOR RECORD

Investigative Photographs
ERA22LA185

Peter Wentz
Air Safety Investigator
Eastern Region Aviation

Photographs provided by the Federal Aviation Administration.



Photograph 1 – Accident Airplane – Right front side of airplane.



Photograph 2 – Accident Airplane – Right aft side of airplane.



Photograph 3 – Accident Airplane – Damaged rudder.