

NTSB ERA22LA192

N919AC

Photo Array



Photo 1: Overview of the helicopter at the accident site (Photo Courtesy of FAA)



Photo 2: Overview of the helicopter at the accident site (Photo Courtesy of FAA)