

NTSB ERA22LA205

N4278B, Maule MX7-180A

Photo Array



Photo 1: Overview of the airplane at the accident site (Pilot Photo)



Photo 2: Overview of the airplane's right wing damage (FAA Photo)



Photo 3: Airplane's right wing tip damage (FAA Photo)



Photo 4: Overview of the right wing damage, leading edge (FAA Photo)



Photo 5: Overview of the right wing damage, trailing edge (FAA Photo)



Photo 6: Overview of the right wing damage, inboard trailing edge (FAA Photo)