



Photo 1 – FAA Digital Photograph. Left Side View of the Airplane Where it came to rest Down the Embankment. Note, only the Top portion of the Fuselage, Vertical Stabilizer and Rudder are Visible.



Photo 2 - FAA Digital Photograph. Right Rear Quartering View of the Airplane Where it Came to Rest down the Embankment. Not Visible are the outer Portion of the right wing, Upper Part of the Vertical Stabilizer and Rudder, and Outer Portion of the Left Wing.



Photo 3 - FAA Digital Photograph. Close-Up View of the Right Wing Taken at the Wingtip Looking Inboard. Note the Compression Wrinkles on the Upper Skin.