



Photo 1 – Digital Photograph From Recovery Company. Right Side View of the Helicopter Following Recovery. Note the Separated Tailboom and Displaced Engine.



Photo 2 - Digital Photograph From Recovery Company. Right Side View of the Helicopter Following Recovery. Note the Structural Damage, Separated Tailboom, and Displaced Main Rotor Assembly.



Photo 3 - Digital Photograph From Recovery Company. Image Taken From Pilot's Seat Showing Location of GPS.