



Photo 1 – Digital Photograph From Pilot. Left Side View of the Airplane Where it Came to Rest. Note the Collapsed Right Main Landing Gear.



Photo 2 - Digital Photograph From Pilot. View of the Collapsed Right Main Landing Gear.



Photo 3 - Digital Photograph From Pilot. Aft View of the Airplane Where it Came to Rest. Note the Compression Wrinkle on the Upper Skin of the Right Side of the Stabilator.



Photo 4 – FAA Digital Photograph. View Showing the Structural Damage to the Right Side of the Stabilator.



Photo 5 - Digital Photograph From Pilot. View Showing the Separation of the Right Main Landing Gear Shock Absorber Rod From the Compressor Fitting.