

MEMORANDUM FOR RECORD

Investigative Photographs
ERA22LA236

Peter Wentz
Air Safety Investigator
Eastern Region Aviation

Photographs provided by the Federal Aviation Administration.



Photograph 1 – Accident Site – Aft view of helicopter.



Photograph 2 – Accident helicopter – Belly view and skids of helicopter.



Photograph 3 – Accident helicopter – Damaged tail boom of helicopter.



Photograph 4 – Accident helicopter – Rotor blades and mast.