

ERA22LA237

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Main Wreckage (Courtesy of FAA)




Photograph 2 - Cockpit (Courtesy of FAA)



Photograph 3 - Propeller and Mixture Controls (Courtesy of FAA)



Photograph 4 - Main Wreckage on Recovery Trailer



Photograph 5 - Left Engine (Courtesy of Lycoming Engines)



Photograph 6 - Right Engine (Courtesy of Lycoming Engines)



Photograph 7 - Left Engine Run



Photograph 8 - Right Engine Run

END